# Infrared Fiber Optic Polymer Bolt Temperature System





- Response Time 10 Milliseconds
- Fiber Optic Cable
- Withstands Pressure up to 30,000 psi
- FM and CSA Approved Intrinsically Safe Models Available Steel Construction
- High Operating Temperature
- Hermetically Sealed for Harsh Environments

The 4121 Polymelt System offers a unique non-contact method of measuring polymer melt temperatures. Unlike thermocouples, its 10 millisecond response time provides unsurpassed real-time temperature data and tighter process control. Since the probe tip is flush with the barrel's ID, it "looks into" the melt and is completely non-intrusive, producing no error due to polymer shear effects or heat sinking.

This compact and rugged system allows maximum installation flexibility and requires a minimum amount of space for installation. The 4121 polymelt system offers a fast and accurate method to monitor polymer temperature in the extruder nozzle or barrel or in the injection molding cavity.

The polymelt transducer system incorporates a chopper stabilizing detector for drift free operation and is directly interchangeable with thermocouple instrumentation such as meters or controllers with cold junction compensation. The 4121 is manufactured using advanced laser



Both models shown smaller than actual size.

soldering technology and incorporates surface-mount devices for exceptional reliability and compactness.

The 4121 polymelt system consists of a patented polymer probe with a rugged, flexible fiber optic cable assembly. The probe tip contains an abrasion resistant sapphire window which is capable of withstanding 30,000 psi pressure. The standard Hastelloy tip allows use on more abrasive polymer materials. The fiber optic assembly easily connects to the transducer. The 4121 polymelt system output ties directly to dataloggers, process controllers, and recorders. It incorporates a digital emissivity control for precise and repeatable setting of emissivity.

### **Specifications**

Temperature Range: 98 to 463°C (210 to 865°F) (in sub-ranges) Temperature Accuracy: ±1% of reading

#### Linearization Accuracy:

±1% of reading or 2°C, 4°F, whichever is greater **Emissivity Control:** 0.10 to 0.99 in 0.01 steps **Output:** 1 mV/° standard, secondary output either 4 to 20 mA, 0 to 10 Vdc, J T/C

Ambient Temperature:

**Model 4121:** 10 to 50°C (50 to 122°F) **Fiber Optics:** 10 to 150°C (50 to 300°F) **Destral Paspage:** 

Spectral Response: 1.0 to 2.7 microns Response Time: 10 ms Power Supply: ±15 Vdc, 100 mA (±0.05% regulation) Power Consumption: 2 W Mating Cable Connector: Bendix PT06A-10-65SR Dimensions: Model 4121: 62 Dia. x 185 L mm (2.43 x 7.3") Fiber Optic Probe: See dimensional diagrams

Weight: Series 4121 Detector: 0.9 kg (2 lb) Fiber Optics: 0.7 kg (1.5 lb)

#### Dimensions: mm (in)

#### Series 2120

Series 2120 standard polymer probe is available in lengths from 165 to 305 mm (6.5 to 12.00") and is installed as shown below. The fiber optic cable is permanently attached to the bolt assembly. The air purge fitting is at 90° from the probe body.

#### Series 2108

\$1290

Series 2108 quick-disconnect polymer probe, measuring as small as 76 mm (3") overall, is used where the available mounting space is at a premium. The fiber bundle exits the probe at a right angle and is easily removable from the probe body by a knurled twist nut. Air purge fitting is at 60° from the probe body.





-A- 1/2-20 UNF-2

3.8 (0.515 MIN,

1

REQUIRED "WELL" MACHINING

45° ±1/2°

(0.750) — MIN, FULL TH'D

LENGTH "L" MINUS A MIN. OF 1/16

#### 4121 Infrared Detectors<sup>†</sup>

## *MOST POPULAR MODEL HIGHLIGHTED!*

To Order (Specify Model Number)				
Model No.	Price	Description Outputs		
4121-G-F-1	\$2195	Infrared detector	1mV/° and 0 to10 Vdc putputs	
4121-G-F-4	2195	Infrared detector	1mV/° and 4 to 20 mA putputs	
4121-G-F-J	2195	Infrared detector	1mV/° and J putputs	
L				

<sup>†</sup>**Note:** A complete system consists of a Series 4121 detector and either the 2120 or 2108 fiber optic probe assembly. You must order at least one detector and one probe from the tables below.

#### Fiber Optic Polymer Bolt Assemblies (Both styles are fitted for air purging)

To Order (Specify Model Number)					
Model No.	Price	Temperature Range	Cable Length		
Fiber Optic Assembly with Standard Polymer Bolt (with fiber optic cable hardwired to bolt)					
2120-[ * ]-2516-T1-7-1-2	\$1170	98 to 316°C (210 to 600°F)	0.3 m (1') fiber optic cable		
2120-[ * ]-2516-T1-7-2-2	1190	121 to 371°C (250 to 700°F)	0.6 m (2') fiber optic cable		
2120-[ * ]-2516-T1-7-3-2	1210	135 to 390°C (275 to 735°F)	1 m (3') fiber optic cable		
2120-[ * ]-2516-T1-7-4-2	1240	154 to 415°C (310 to 780°F)	1.2 m (4') fiber optic cable		
2120-[ * ]-2516-T1-7-5-2	1265	163 to 438°C (325 to 820°F)	1.5 m (5') fiber optic cable		
2120-[ * ]-2516-T1-7-6-2	1290	174 to 463°C (345 to 865°F)	1.8 m (6') fiber optic cable		
Fiber Optic Assembly with Quick Disconnect Polymer Bolt (with right angle fiber optic cable for disconnecting fiber optic cable from bolt)					
2108-[ ** ]-2008-0001-1	\$1290	98 to 316°C (210 to 600°F)	0.3 m (1') fiber optic cable		
2108-[ ** ]-2008-0001-2	1320	121 to 371°C (250 to 700°F)	0.6 m (2') fiber optic cable		
2108-[ ** ]-2008-0001-3	1360	135 to 390°C (275 to 735°F)	1 m (3') fiber optic cable		
2108-[ ** ]-2008-0001-4	1390	154 to 415°C (310 to 780°F)	1.2 m (4') fiber optic cable		
2108-[ ** ]-2008-0001-5	1425	163 to 438°C (325 to 820°F)	1.5 m (5') fiber optic cable		
2108-[ ** ]-2008-0001-6	1460	174 to 463°C (345 to 865°F)	1.8 m (6') fiber optic cable		

\* Insert 6 to 12" probe length.

\*\* Insert 3 to 12" probe length.

Ordering Examples: 4121-G-F-J, Series 4121 infrared detector with 1 mV/° and Type J thermocouple outputs, \$2195.

2108-3-2008-0001-3, quick-disconnect polymelt probe, 3" long, with a 3' fiber optic cable, and a 135 to 390°C (275 to 735°F)

temperature range, \$1360. \$2195 + \$1360 = \$3555. 4121-G-F-4, Series 4121 infrared detector with 1 mV/° and 4 to 20 mA outputs, \$2195. 2120-7-2516-T1-7-4-2, standard polymelt probe, 7" long, with a 4' fiber optic cable, and a 154 to 415°C (310 to 780°F) temperature range, \$1240. \$2195 + \$1240 = \$3435.

7.92 (0.312) 7.97 (0.314) DIA. A .002 DIA. 10.69 (0.421) A .003 DIA.

5.71 (0.225) MIN

9.56 (0.375)

## omega.co.uk®

Your One-Stop Source for Process Measurement and Control!

Freephone 0800 488 488 I International +44(0) 161 777 6622 I Fax +44(0) 161 777 6622 I Sales@omega.co.uk

## www.omega.co.uk



UNITED STATES www.omega.com 1-800-TC-OMEGA Stamford, CT.

CANADA www.omega.ca Laval(Quebec)

1-800-TC-OMEGA

### GERMANY

www.omega.de Deckenpfronn, Germany 0800-8266342 UNITED KINGDOM www.omega.co.uk Manchester, England 0800-488-488 +44-(0)161-777-6611

> FRANCE www.omega.fr 0800-466-342

BENELUX www.omega.nl 0800-099-33-44



## More than 100,000 Products Available!

## Temperature

Calibrators, Connectors, General Test and Measurement Instruments, Handheld Instruments for Temperature Measurement, Ice Point References, Indicating Labels, Crayons, Cements and Lacquers, Infrared Temperature Measurement Instruments, Recorders, Relative Humidity Measurement Instruments, PT100 Probes, PT100 Elements, Temperature & Process Meters, Timers and Counters, Temperature and Process Controllers and Power Switching Devices, Thermistor Elements, Probes and Assemblies, Thermocouples, Thermowells and Head and Well Assemblies, Transmitters, Thermocouple Wire, RTD Probes

## Flow and Level

Air Velocity Indicators, Doppler Flowmeters, Level Measurement, Magnetic Flowmeters, Mass Flowmeters, Pitot Tubes, Pumps, Rotameters, Turbine and Paddle Wheel Flowmeters, Ultrasonic Flowmeters, Valves, Variable Area Flowmeters, Vortex Shedding Flowmeters

## pH and Conductivity

Conductivity Instrumentation, Dissolved Oxygen Instrumentation, Environmental Instrumentation, pH Electrodes and Instruments, Water and Soil Analysis Instrumentation

## Data Acquisition

Communication Products and Converters, Data Acquisition and Analysis Software, Data Loggers Plug-in Cards, Signal Conditioners, USB, RS232, RS485, Ehernet and Parallel Port Data Acquisition Systems, Wireless Transmitters and Receivers

## • Pressure, Strain and Force

Displacement Transducers, Dynamic Measurement Force Sensors, Instrumentation for Pressure and Strain Measurements, Load Cells, Pressure Gauges, Pressure Reference Section, Pressure Switches, Pressure Transducers, Proximity Transducers, Regulators, Pressure Transmitters, Strain Gauges, Torque Transducers, Valves

## Heaters

Band Heaters, Cartridge Heaters, Circulation Heaters, Comfort Heaters, Controllers, Meters and Switching Devices, Flexible Heaters, General Test and Measurement Instruments, Heater Hook-up Wire, Heating Cable Systems, Immersion Heaters, Process Air and Duct, Heaters, Radiant Heaters, Strip Heaters, Tubular Heaters